

ARC WELDING



ME 353 Presentation

11-3-2000

Presented by Damon Ogden

OUTLINE



- What is Arc Welding
- The four most common types
- Non destructive testing
- Design considerations
- Strength
- Safety

Feel free to ask questions at any questions at any time.



Arc Welding


- Welcome to the world of WELDING



What is Arc Welding?

An electric **arc** between the and **electrode** and the work piece generates heat. Sufficient heat is generated to melt the **work pieces** together.





Electricity

The range of welding current used can be from 5 to 500 amps. The voltage ranges from 20 to 30 volts, AC or DC. Both are determined by the material thickness.

A 60 watt light bulb draws .5 amps.


Four Common Types of Welding



- Stick SMAW (shielded metal arc welding)
- Mig GMAW (Gas Metal Arc Welding)
- Flux-Core FCAW (Flux-core Arc Welding)
- Tig GTAW (Gas Tungsten Arc Welding)

Characteristics

Each welding process has unique traits that make it more suited for particular processes



Some Terms



Electrode

This is where the current passes from the welder to the work piece.

There are two types:

- 1) Contact/consumable
- 2) Non Contact

More Terms




Atmospheric protection

There are 2 types:

- 1) Shielding Gas
- 2) Flux

Stick Weld Schematic




Stick Welding



- Uses a consumable electrode (rod), with a flux coating.
- Stick welding requires a moderate to high skill level.
- Advantages:
 - Portable
 - Can be used in all environments
 - Not as dependent on surface preparation

Stick Welding



Electrode




Arc



Stick welder joins sections of oil pipe in Alaska.

MIG WELDING SCHEMATIC



Mig Welding

A decorative graphic on the right side of the slide, resembling a welding torch flame or a MIG welding arc. It is a horizontal, elongated shape with a color gradient from dark blue on the left to bright yellow and orange on the right, tapering off to the right.

- The electrode is a wire, fed from a spool to the end of the “gun”.
- A shielding gas is used to give atmospheric protection.
- This process requires a low to moderate skill level.

Advantages:

- 1) Very fast process
- 2) Easy to learn

Disadvantages:


- 1) Weld area must be protected from air movements

Mig Welding



MIG welding stainless steel

Flux Core Schematic



Flux Core



- This process is a hybrid between Mig and Stick welding.
- It is the same process as Mig welding, except instead of a shielding gas, there is flux in welding wire.


Advantages:

- 1) Can be done in all environments

Disadvantages:

- 1) Requires additional clean up to remove flux

TIG WELDING SCHEMATIC



Tig Welding

A decorative graphic on the right side of the slide, resembling a welding torch flame or a heat gradient. It features a horizontal bar with a color gradient from dark blue on the left to bright yellow and orange on the right, with a soft, glowing aura around it.

- There is a Tungsten electrode through which the current is passed. (Melting pt. = 3700 degrees K)
- Argon is used as a shielding gas.
- Requires the highest skill level.

Advantages:

- 1) Nearly all metals can be welded using this process.
- 2) Very precise

Disadvantages:

- 1) Slow process

Tig Welding



TIG welding a Nascar chassis together.

PROBLEM 1



A semi-truck is parked along side I-80 with a broken air brake mount on it's trailer. The mount is made out of standard steel. The truck can not be moved until the repair is made. Which welding process, (MIG, TIG, Stick, Flux Core) could be used to make the repair? Discuss what factors were involved in your selection process.

Answer on page 4 of handout

ANSWER TO PROBLEM 1



There are two process that could be used to make the needed repair. Those two processes are **flux core**, and **stick** welding. Because the repair had to take place in the field, a process must be used that **did not require an external shielding gas**.

Both of the processes are equally suited to make the repair. Stick welding requires a higher skill level than flux core, so the operator skill level is a factor.

Automatic/ Robotic Welding




- Can be done using the MIG or TIG processes
- Used when there are long, reproducible weld joints
- It can be used where the environment is hazardous to humans
- Saves time and money



Weld Head

This robotic TIG welder is sealing nuclear waste storage containers.



An automatic Multi-Head Mig welder joins sections of pipe together.

Radiography




- A non-destructive process to test welds using X-Rays

Welds with internal flaws can lead to failures



DANGER



Radiograph of a steel pipe

INTERNAL
UNDERCUT


Outside pipe
wall

Inside pipe wall


Undercut

Porosity

POROSITY



And now for a short movie



This will show Mig welding and will
show some common joint types

Things to consider in weld design



- Material selection is critical for success
- Some factors that influence selections are:

Strength

Weight


Cost

Service environment

Location where the welding is going to occur


Other things to ponder

- Welding apparatuses have physical size and that can limit weld design



Design Considerations

Planning must be done to allow joints to be welded



Because of poor design this weld is difficult to complete successfully.


Weld Strength



- A “good” weld is stronger than the parent material
- Welding creates stresses at the weld boundaries
- The stresses will always lead to a failure at the weld edges, not in the weld itself


Effects of weldments on fatigue strength

Avoid abrupt changes in stiffness




1 million cycles = 25800 psi
2 million cycles = 22800 psi

The diagram shows a horizontal orange beam with red arrows at both ends. A vertical orange bar is attached to the center of the beam. The transition between the beam and the bar is smooth, with a rounded fillet. A blue arrow points to the transition area.



1 million cycles = 25400 psi
2 million cycles = 18900 psi

The diagram shows a horizontal orange beam with red arrows at both ends. A vertical orange bar is attached to the center of the beam. The transition between the beam and the bar is sharp, with a 90-degree corner. A blue arrow points to the transition area.



1 million cycles = 22900 psi
2 million cycles = 13100 psi

The diagram shows a horizontal orange beam with red arrows at both ends. A vertical orange bar is attached to the center of the beam. The transition between the beam and the bar is sharp, with a 90-degree corner. There are welds indicated by red lines at the transition. A blue arrow points to the transition area.

43% reduction in fatigue strength



Welding Safety

- Arc rays can injure eyes causing scar tissue and even blindness with prolonged exposure
- Arc rays emit UV light and have been found to cause skin cancer

SPF 1000 sun block is recommended

- High levels of current can cause electrocution
- Extreme heat can cause severe burns

CAUTION



Cancer Agent
Present

Welding Safety

Welding fumes are hazardous to your health!

- Short term effects include:
Nausea, dizziness, irritation of the nose, throat and eyes.
- Long term effects include:
Iron deposits in the lungs, central nervous system effects, Bronchitis and Cancer

PROBLEM 2



Assume that you are an Engineer who has designed a device, and you must now specify a particular weld process. Discuss some of factors that could affect the decision.

ANSWER TO PROBLEM 2

Answers included on page 5 of the handouts

Material to be welded:

- Some materials require special processes that take more time and skill than others.

Number of welds, or length of weld:

- Some welding processes are faster than others.
- MIG/Flux core are fastest, then Stick, then TIG

Weld bead size:

- Tig welding produces a smaller weld than mig or stick.

If space is critical, then a small weld bead is desirable.

PROBLEM 2 CONTINUED



Weld bead size:


- Tig welding produces a smaller weld than mig or stick. If space is critical, then a small weld bead is desirable.

Location where welding is to occur:


- See question one.

Operator skill level:

- The four welding processes require different skill levels. TIG highest, MIG/Flux core lowest.



*Any
Questions ?*



Albert Einstein once said:

“Education is what remains when one has forgotten everything he learned in school”

This concludes the presentation

